

Error memory

Date: 3/19/26, 9:54 PM
VIN: WZ1DB0C05NW049076

01 Crash Safety Module

5 errors

930A34: UpFront: Right airbag front sensor: Short circuit to minus

930A2A: UpFront: Left airbag front sensor: Short circuit to minus

C9540F: Status function ActivePDC: TimeOut

C95411: Status function PDC: TimeOut

C95439: CTA display: Timeout

06 All-round vision camera

1 error

CA9411: BOTSCHAFTSFEHLER_0x3532_0x0001_
BMW_DASS_ParkdistanceInformation_TIMEOUT

0F Controlled self-locking differential

3 errors

CCEC20: Signal (outside temperature, 252.1.4) invalid TEMP_EX, transmitter Kombi / Kombi_Basis

482BAE: Lock: initialization could not be completed

CCEC19: Signal (actual wheel speed, 46.0.1) invalid, transmitter DSC_IB_BRS

12 Digital Motor Electronics

12 errors

030E08: Power management: Battery falls below upper startability limit

10B107: Outside temperature sensor: short circuit to ground

CDA059: FlexRay, message (information data target object speed control 2, 125.0.16): missing

CDA038: FlexRay, message (information data target object speed control, 71.7.32): missing

CDC31C: Flexray, message (target display vibration warning lane change, 237.2.4): missing

10B105: Outside temperature sensor, signal: CAN message faulty

1E0308: Idle control, plausibility, cold start: speed implausible

21A511: Starting system, pinion starter: timeout

216116: Pinion starter: attempted start detected in the event of a fault in the combustion system

180001: Catalytic converter: efficiency below limit value

12B701: Heating lambda probe2 bank1, function: internal resistance too high

232007: Outside temperature sensor, plausibility, cold start: temperature too high

29 Dynamic Stability Control (DSC)

4 errors

480A12: Brake pad sensor - rear axle - wear limit reached

D3542C: Signal (outside temperature, ID: A_TEMP) invalid

48069E: RDCi calibration wheel detection not possible

4809EB: RDCi wheel electronics (position unknown) no reception

37 Top HiFi amplifier

1 error

B7F4BC: No RADON signal although the engine is running

39 Virtual integration system

2 errors

483903: Power supply - global undervoltage external

D74518: FAS-CAN Control Module Bus OFF

40 Body Domain Controller

8 errors

804081: Production readiness to drive: faulty

8040A9: Start-stop button SST: incorrect operation (oblique pressure)

8040C6: KL30F: Reset request due to closed-circuit current violation

8040D2: PWF status activation: Parking BN not ok

8044A3: Horn: short circuit to ground

D91CCF: CAN message, front area monitoring FCM (HDWOBS_FCM): Timeout

D91CD0: CAN message, front area monitoring PPP (HDWOBS_PPP): Timeout

D91DFC: CAN message, target display vibration warning lane change (TAR_DISP_VIB_WARN_LNCH): Timeout

56 Roof function center

1 error

801A56: Anti-theft alarm system: Panic alarm - details in the panic memory

5D Camera-based driver assist system

4 errors

800AC8: Permanent calibration error

E05615: 0xE05615 - Signal error - 0x1535 - 0x0001 - BMW.INFRASTRUCTURE - EnvironmentalInformation - signal invalid

E05420: 0xE05420 - Message error - 0x3538 - 0x0001 - BMW.DASS - DriverAssistanceComfortAndSecurity - Timeout

800ABF: KAFAS camera: field of view temporarily disturbed

60 Instrument panel

2 errors

B7F654: Outside temperature sensor has a short circuit to ground

E12C3B: DME DDE interface (status automatic engine start-stop, 0x30B): signal invalid

63 Headunit High

1 error

B7F8F6: HDCP: authentication failed

76 Vertical dynamics platform

4 errors

4828E5: Valve Coil - Rebound - Front Right Open Line

4828EC: Valve Spool - Rebound - Front Left Open Line

4828F6: Valve coil - rebound - rear right open pipe

4828FF: Valve spool - rebound - rear left open pipe

78 Integrated automatic heating / air conditioning system

1 error

E71417: Signal (temperature_outside in 0x2CA): received invalid