

# Error memory

Date: 3/20/26, 8:36 AM  
VIN: WZ1DB0C05NW049076

## 01 Crash Safety Module

### 5 errors

C9540F: Status function ActivePDC: TimeOut

C95411: Status function PDC: TimeOut

C95439: CTA display: Timeout

930A2A: UpFront: Left airbag front sensor: Short circuit to minus

930A34: UpFront: Right airbag front sensor: Short circuit to minus

## 06 All-round vision camera

### 1 error

CA9411: BOTSCHAFTSFEHLER\_0x3532\_0x0001\_  
BMW\_DASS\_ParkdistanceInformation\_TIMEOUT

## 12 Digital Motor Electronics

### 6 errors

10B107: Outside temperature sensor: short circuit to ground

CDA038: FlexRay, message (information data target object speed control, 71.7.32):  
missing

CDA059: FlexRay, message (information data target object speed control 2, 125.0.16):  
missing

CDC31C: Flexray, message (target display vibration warning lane change, 237.2.4):  
missing

216116: Pinion starter: attempted start detected in the event of a fault in the combustion system

10B105: Outside temperature sensor, signal: CAN message faulty

## 29 Dynamic Stability Control (DSC)

### 2 errors

D3542C: Signal (outside temperature, ID: A\_TEMP) invalid

480A12: Brake pad sensor - rear axle - wear limit reached

## 39 Virtual integration system

### 2 errors

483903: Power supply - global undervoltage external

D74518: FAS-CAN Control Module Bus OFF

## 40 Body Domain Controller

### 3 errors

D91CCF: CAN message, front area monitoring FCM (HDWOBS\_FCM): Timeout

D91CD0: CAN message, front area monitoring PPP (HDWOBS\_PPP): Timeout

D91DFC: CAN message, target display vibration warning lane change (TAR\_DISP\_VIB\_WARN\_LNCH): Timeout

## 60 Instrument panel

### 2 errors

B7F654: Outside temperature sensor has a short circuit to ground

E12C3B: DME DDE interface (status automatic engine start-stop, 0x30B): signal invalid

## 76 Vertical dynamics platform

### 4 errors

4828E5: Valve Coil - Rebound - Front Right Open Line

4828EC: Valve Spool - Rebound - Front Left Open Line

4828F6: Valve coil - rebound - rear right open pipe

4828FF: Valve spool - rebound - rear left open pipe

## 78 Integrated automatic heating / air conditioning system

### 1 error

E71417: Signal (temperature\_outside in 0x2CA): received invalid